

# FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)  
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.  
8m x 6.2m x 3.3m - 2 No:s  
6m x 6.2m x 3.3m - 2 No:s  
5.9m x 6.2m x 3.3m - 1 No.  
3.8m x 6.2m x 3.3m - 1 No.  
6.1m x 6.1m x 3.3m - 6 No.
5. Period for which the certificate is issued
6. Nature of defects , if any
  - a) Foundation and basement
  - b) Superstructure
  - c) Doors and Windows
  - d) Wood work wrought and put up
  - e) Roof
  - f) Flooring
  - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner

GIREESHMA PRADEEP  
MIC English School  
Akaladu, Theissur district.  
Permanent  
3.05m x 6.15m x 3.3m - 1 No.  
6.00m x 6.15m x 3.3m - 6 No:s  
6.10m x 6.15m x 3.3m - 2 No:s  
6.10m x 3.60m x 3.3m - 2 No:s  
2019 - 2020.

Miscellaneous cracks on flooring  
only

No

Yes

Sound under normal climatic conditions


Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on 19.07.19 and found to be fit / unfit to conduct classes, for the period 2019-2020 for the reasons stated above.

Place: Edalika, ea

Date: 20.07.19



ASSISTANT ENGINEER  
LSGD SECTION  
PUNNAYOOR GRAMA PANCHAYATH

Assistant Engineer